





TECHNICAL REPORT M-308 February 1982

INSULATION RETROFIT UNDER LOW-SLOPE ROOFS

AD A113802

by Myer J. Rosenfield Denald E. Brotherson





Approved for public release; distribution unlimited.

82

The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official indorsement or approval of the use of such commercial products. The findings of this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

DESTROY THIS REPORT WHEN IT IS NO LONGER NEEDED
DO NOT RETURN IT TO THE ORIGINATOR

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

| Γ | REPORT DOCUMENTATION | READ INSTRUCTIONS BEFORE COMPLETING FORM | |
|-----|---|---|--|
| ٣ | REPORT NUMBER | | 3. RECIPIENT'S CATALOG NUMBER |
| L | CERL-TR-M-308 | 10,703 80 | 7 |
| 4. | TITLE (and Subtitle) | | 5. TYPE OF REPORT & PERIOD COVERED |
| | INSULATION RETROFIT UNDER LOW-SLO | PE ROOFS | FINAL |
| | | | 6. PERFORMING ORG. REPORT NUMBER |
| 7. | AUTHOR(a) | | 8. CONTRACT OR GRANT NUMBER(*) |
| 1 | Myer J. Rosenfield | | Interagency Agreement No. |
| 1 | Donald E. Brotherson | | DE-A105-800R20724 |
| 9. | PERFORMING ORGANIZATION NAME AND ADDRESS U. S. ARMY | | 10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS |
| ł | CONSTRUCTION ENGINEERING RESEARCH | LABORATORY | |
| l | P. O. BOX 4005, Champaign, IL 618 | | |
| 11. | CONTROLLING OFFICE NAME AND ADDRESS | | 12. REPORT DATE |
| ļ | | | February 1982 |
| | | | 13. NUMBER OF PAGES 26 |
| 74 | . MONITORING AGENCY NAME & ADDRESS(If differen | t from Controlling Office) | 15. SECURITY CLASS, (of this report) |
| | | | UNCLASSIFIED |
| | | | 15a. DECLASSIFICATION/DOWNGRADING SCHEDULE |
| 14 | DISTRIBUTION STATEMENT (of this Report) | | |

16. DISTRIBUTION STATEMENT (of this Report)

Approved for public release; distribution unlimited.

17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)

18. SUPPLEMENTARY NOTES

Copies are obtainable from the National Technical Information Service Springfield, VA 22161

19. KEY WORDS (Continue on reverse side if necessary and identify by block number)

Roofs thermal insulation

20. ABSTRACT (Courthous an reverse shift if necessary and identity by block number)

This investigation was conducted to identify and evaluate complete systems for applying insulation to the underside of existing low-slope roofs. Criteria were developed to evaluate several systems identified by a market survey. Of the systems evaluated, it was found that only six meet the requirements for this type of application: two are sprayed systems, two are board-applied, and two use proprietary accessories to attach the system to the structure.

DD 1 JAN 79 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED


| UNITY CLASSIFICAT | ON OF THIS PAGE(When I | Data Entered) | | |
|-------------------|------------------------|---------------|------|--|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

FOREWORD

This investigation was performed by the Engineering and Materials Division (EM). U.S. Army Construction Engineering Research Laboratory (CERL) at the request of the U.S. Department of Energy (DOE). The work was completed under Interagency Agreement No. DE-AI05-800R20724. Mr. George Courville was the DOE Project Monitor.

Appreciation is expressed to B. K. Miles and the late James N. Robinson of the Union Carbide Corporation, Oak Ridge, TN, for their assistance in the investigation, and to Mr. Philip B. Shepherd of the Johns-Manville Corporation for performing the surveys.

Dr. R. Quattrone is Chief of CERL-EM. COL Louis J. Circeo is Commander and Director of CERL, and Dr. L. R. Shaffer is Technical Director.



CONTENTS

| | DD FORM 1473 | 1 |
|---|---|------------|
| | FOREWORD | 3 |
| | LIST OF TABLES AND FIGURES | 5 |
| 1 | INTRODUCTION | , 7 |
| 2 | LITERATURE AND MARKET SURVEY AND CRITERIA DEVELOPMENT Literature Survey Market Survey Criteria Development | . 8 |
| 3 | SURVEY RESULTS | . 9 |
| 4 | DESCRIPTION OF SYSTEMS | . 9 |
| 5 | FIELD AND SITE INVESTIGATIONS | . 13 |
| 6 | SUMMARY OF SYSTEMS | . 17 |
| 7 | CONCLUSIONS | . 18 |
| | APPENDIX A: Market Survey Questionnaire APPENDIX B: Field Information Used for Development of Low-Slope Retrofit | 20 |
| | Insulation Evaluation Criteria | 24 |
| | APPENDIX C: TIMA Tests on Sprayed Cellulose Insulation | 26 |
| | DISTRIBUTION | |

TABLES

| Number | Page |
|---|------|
| l Comparison of Insulation Retrofit Systems | 17 |

FIGURES

| Numt | Page | |
|------|---|-----|
| 1 | Typical Metal Building | . 7 |
| 2 | Sprayed Cellulose Insulation | 10 |
| 3 | Celotex System for Direct Fastening to Roof Purlins | 11 |
| 4 | Celotex Suspended Grid System | 11 |
| 5 | Lisi America Isophenol Board | 12 |
| 6 | Johns-Manville "Money-Clip" System | 13 |
| | Completed "Money-Clip" Installation | 14 |
| | Owens-Corning Fiberglas "Energy Miser" System | 14 |
| 9 | Deteriorated Sprayed Cellulose Insulation | 15 |
| 10 | Insulation Batts Supported on Chicken Wire | 15 |
| 11 | Installation of Batts at White Sands Missile Range | 16 |

INSULATION RETROFIT UNDER LOW-SLOPE ROOFS

1 INTRODUCTION

Background

Millions of square feet of low-slope roofs have little or no thermal insulation to minimize heat losses and gains. Many of these roofs are on "metal buildings," which have steel frames with steel decking supported on purlins (see Figure 1). Many low-slope roofs use a bar-joist/steel-deck structural system, while others use wood or concrete. These buildings can be thermally upgraded if the owner is willing to remove the existing roof system and apply a new roof-insulation system. Sometimes, all or part of the existing roof-insulation system can be salvaged.

An insulation retrofit system that applies the material below the deck is needed for buildings where budget or other considerations prohibit the above-deck approach. These buildings exist in all parts of the country and have many uses (e.g., a classroom, a maintenance building, or a warehouse). Such a variety of uses demands that the retrofit system fulfill many requirements. For example, moisture resistance, fire resistance, appearance, and impact resistance are characteristic needs which will vary with occupancy and climate. In addition, the cost and longevity of a system will affect decisions about whether it should be installed.

The National Program for Building Thermal Envelope Systems and Insulating Materials, which is

directed by the U.S. Department of Energy (DOE) and managed by Union Carbide Corporation's Nuclear Division, is identifying and evaluating commercially available products that can be used to thermally upgrade low-slope roofs from the underside. The DOE requested technical support for this project from the U.S. Army Construction Engineering Research Laboratory.

Objective

The objective of this report is to identify and develop criteria to evaluate commercially available products and proven techniques for installing insulating systems to the underside of low-slope roof structures.

Approach

Three major tasks were performed to accomplish this objective:

- 1. The market was surveyed to identify all commercially available systems or techniques that could be used to thermally enhance the roof system without disturbing or removing the existing roof covering. A preliminary analysis was made of all such systems, using technical merit and applicability as criteria; significant and/or appropriate systems were then selected for further evaluation.
- 2. Selected systems were evaluated using criteria specifically developed for this study. This included site inspections of the products or techniques (where feasible), interviews with users and installers, an analysis of manufacturers' literature, and where possible, a determination of installed costs.
- 3. The data obtained in Tasks 1 and 2 were summarized and documented.




Figure 1. Typical metal building. (From Energy Saving Insulation Systems for Pre-Engineered Metal Buildings [Celotex], p 3.)

Scope

This investigation was horized to systems applied to the underside of the existing roof system. No attempt was made to evaluate the systems other than reporting their attributed use, their applicability to specific projects was not appraised.

2 LITERATURE AND MARKET SURVEY AND CRITERIA DEVELOPMENT

Literature Survey

The literature was start and to identify products and systems currently used or being developed for insulation retrofit. Three computer search sources were used to locate appropriate iterature: (1) National Technical Information Service (Springfield, Virginia), (2) Compandex Engineering (1)dex, inc. (New York, New York), and (3) Issuee Data Courier, Inc. (Louisville, Kentucky).

Market Survey

A mailing list of regulate torers, trade essociations, distributors, and technical codesionals was compiled; a questionnaire requesting input for the market survey was then sent to each (See Appendix A.) Sixty responses were received, of mess 32 had applicable products available. Most or those positive respondents provided trade hieractic 3 reconficul information about their products. Investigators also reviewed section 7.15 of Sweet's Catalogue¹ (1960 through 1980) for other products and/or systems.

Several telephone and personal interviews with manufacturers of insulating materials, trade association officials, members of the National Research Council (Canada), and the Sweet's Division of McGraw-Hill (trade literature) supplemented the mail survey. The market survey was extended to Europe, Australia, and Japan through overseas contacts.

Criteria Development

To evaluate the literature and market survey results, criteria for comparing the various identified products and applications were established. It was very difficult to quantify the criteria because there are few similar requirements. For example, toxicity of fumes from

burning insulation may be a concern in certain equipancies; however, there are no accepted test methods for establishing toxicity levels. For many of the criteria, owner or occupancy requirements will gove in the acceptance or rejection of a product or system. The quality of "appearance" is a good example of this. In residential, office, or other spaces used primarily for personnel occupancy, the surface appearance will be more important than in industrial space, where, for example, chemical reaction to the interior environment may be emphasized. For commercial space, a product's cost vs. its life-expectancy may be the governing criterion.

The following 17 criteria were established for evaluating the products or systems. These criter a represent the most common requirements encounter d in the field. Appendix B contains the detailed information obtained from field personnel from which the criteria were developed. (The order of their listing does not reflect their relative importance in the evaluation procedure.)

- 1. Thermal value conductivity or resistance. It is property of insulation which determines the retent: n of heat within the building.
- 2. Moisture effects on thermal value. Resistan e may depend on the moisture content of the insulatio:
- 3. Aging effects on thermal value, Resistance $n \cdot y$ tend to change as the insulation ages.
- 4. Temperature effects on thermal value. Conductivity is a function of temperature, and affe ts insulating value.
- 5. Water vapor transmission rate. A high rate m, y cause an accumulation of moisture within the material, which may affect its resistance.
- 6. Effect of exposure on performance. Resistance may tend to change with length of exposure.
- 7. Physical shape: boards, batts, loose, etc. Affects method of installation.
- 8. Weight. Must be considered when supporting insulation from existing structures.

¹ Sweet's Catalogue File (Mc(naw Hill Information Systems Co.).

- 9. Compressive strength. May be necessary to resist compressive forces of fastening devices.
- 10. Reaction to chemicals. Some chemicals in atmosphere may change resistance values.
- 11. Fire resistance qualities. Insulation should resist burning.
- 12. Toxicity of fumes from burning. May be important if building being insulated is occupied.
- 13. Appearance. Important if exposed to view in occupied spaces.
- 14. Method of application. Should be considered based on occupancy requirements of building.
- 15. Compliance with building codes. Required in order to obtain building permits.
 - 16. Cost. How will initial cost affect amortization?
 - 17. Other (e.g., life expectancy, years in use, etc.).

3 SURVEY RESULTS

Literature Survey

The computer retrieved 312 citations. Of these, 58 appeared to be of value; however, upon review, only a few produced pertinent data. Several articles pointed out potential problems with condensation, and some provided guidelines for balancing the amounts of insulation above and below possible vapor retarders. One article² described new systems for thermally upgrading metal buildings, in which mineral fiber insulations are supported on special hardware designed to interface with the steel purlins of the deck system. Investigators identified three possible sources for these systems and requested information from them for the market survey.

Market Survey

The market survey revealed many ways of thermally upgrading existing roof systems. Unfortunately, very few products that can be used under the roof deck are available; most require alteration or removal of

the existing roof covering. Perhaps the most important finding of the market survey was that the "under deck" market was primarily controlled by the insulation installers, not by the roofing contractors. Only two manufacturers have developed a complete system, and only one of these systems is currently being marketed. In all other cases, the installer/applicator assembles or fabricates a system from products of different manufacturers.

The survey identified six "systems": two are sprayed, two use board stock, and two use proprietary accessories to attach the system to the underside of the structure. These systems are described in detail in Chapter 4.

4 DESCRIPTION OF SYSTEMS

Sprayed Cellulose

Two systems apply cellulose insulation by spraying (see Figure 2).

Thermocon Insulation, manufactured by Thermo Products Company, is a cellulose material with a density of about 2.5 lb/cu ft (40 kg/m³). An adhesive material (Thermobond) is added to bond the cellulose to the surface and to provide a monolithic surface. When tested in 1974 according to UL 723 specifications³, the material exhibited a flame spread rating of 5 and a smoke-developed rating of 0. The test data indicated a thermal resistance R-value ranging between 4.44 and 5.53 per inch (25.4 mm) thickness at 3.23 to 3.26 lb/cu ft (51.7 to 52.2 kg/m³) density and an R-value of 3.89 at 2.6 lb/cu ft (41.6 kg/m³). The advertised R-value is 4.59 at 2.5 lb/cu ft (40 kg/m³).

National Cellulose markets a product similar to Thermocon. However, test data generated by the Thermal Insulation Manufacturer's Association (TIMA) indicate thermal values that are substantially lower than the data for Thermocon given above. (See Appendix C.)

Board-Applied

The Celotex Corporation markets a foil-faced insulation board which has a glass-fiber-reinforced, polyisocyanurate plastic core. The plastic foam core

² "Hidden Market: Insulating Metal Roofs," Roofing. Siding, and Insulation, Vol. 57 (October 1980), pp 74-76.

³Standard Test Method for Fire Hazard Classification of Building Materials, UL 723 (Underwriters' Laboratory, October 1979).



Figure 2. Sprayed cellulose insulation.

has a uniform cellular structure. The aluminum facings provide vapor retarders and are available in the following finishes for different applications:

Embossed -white-coated and embossed one side; aluminum on the other side; washable; recommended for ex-

posed applications.

Heavy-Duty --white-coated on foil facer for exposed locations where greater contact resistance is needed.

Thermax Plus – white-coated with 0.019-in. (0.48-mm)-thick aluminum sheet laminated to one side; recommended for areas subject to physical abuse.

Satin Finish -smooth, white-tinted finish; least

expensive; washable; recommended where appearance is not of prime importance.

Plain Factory

& Cavity Wall -recommended for concealed applications.

The boards are available in thicknesses ranging from 1/2 in. (13 mm) to 2 1/4 in. (57 mm). The standard width is 4 ft (1220 mm) with lengths up to 40 ft (12.2 m) available. Thermax Plus is also available in thicknesses of up to 3 in. (76 mm).

Aged R-values for the product are 7.2 at 75°F (24°C) mean temprature, 8 at 40°F (4.5°C), and 6.5 at 110°F (43°C).


The recommended application technique uses either self-tapping fasteners to secure the boards

directly to the roof purlins (Figure 3), or a suspended grid system (Figure 4). Washers prevent damage to the board surface. The joints are then covered with a pressure-sensitive aluminized tape for vapor retardation. Supplemental glass fiber batts may be installed above the boards to further increase R-values.

Lisi America, Inc., markets a rigid foam board made of phenolic resins (Isophenol). As with iso-

cyanurates and urethanes, a fluorocarbon blowing agent is used to expand the plastic. The material is produced in densities ranging from 2 to 4 lb/cu ft (32 to 64 kg/m³) with an R-value of 5 at 2.5 lb/cu ft (40 kg/m³) density. It is usually supplied in 2- X 3- X 4-ft (610- X 915- X 1220-mm) "buns," or in slabs of any thickness. The boards are rigid with a smooth finish but are relatively fragile and will shatter or break easily. The material will not absorb water or support

For New Construction and Retro Fit of Existing Buildings. Installation of Thermax® insulation Board Below Roof Puttins and Inside Wall Girls



Note:

Where Thermax Insulation Board is installed below roof purlins, venting provisions are advised. Adequate venting can be achieved at eaves and ridge.

Figure 3. Celotex system for direct fastening to roof purlins. (From Energy Saving Insulation Systems for Pre-Engineered Metal Buildings [Celotex], p 12.)




Figure 4. Celotex suspended grid system. (From Energy Saving Thermax Grid Suspension System for Commercial Buildings [Celotex], p 2.)

combustion, is resistant to chemicals, and is noncorrosive to metals. The boards are designed to be applied using mastics as adhesives (Figure 5).

Proprietary Accessories

Two systems use patented accessory devices to install the insulation system.

The Johns-Manville Corporation's "Money-Clip" system is a vinyl extrusion that clips onto the roof purlins and supports a fiberglass board with a vinyl facing and a 5-1-2-in. (140-mm)-thick, low-density, fiberglass insulating batt. End caps and T-sections for joining panels complete the accessory package (Figure 6).

The installed system provides an R-value of about 20. It has a high-impact-resistant surface with a low permeance rating and a white surface for good light reflectance. The appearance is "clean," since no fasteners are visible (Figure 7). The manufacturer claims that this system can be installed quickly.

The Owens-Corning Fiberglas (OCF) Corporation's "Energy Miser" system is particularly designed for metal buildings (Figure 8). The system uses a clip that attaches to the roof purlin and supports a metal roller.

The roller-clip assembly can be adjusted to support a variety of insulation thicknesses without compressing them at the purlin points. The insulation is OCF "Certified R Faced Metal Building Insulation" available in R-6 or R-1.3* thickness. The cavity above the insulation can be filled with additional insulation ranging from 3 to 6 in. (75 to 152 mm) thick.

The manufacturer indicated that the system offers good moisture vapor control, although no provision is mentioned for scaling joints between adjacent runs of insulation. This system was announced as being ready for distribution in June of 1981.4

Contractor-Designed Systems

The survey identified several contractor-designed systems that use various types of mechanical fastening devices, in which either adhesive-applied pins or stud-welded pins are attached to the underside of the deck. Batt-type insulation is than pushed onto the pins and secured by washers applied over the pins. Sometimes chicken-wire is applied below the insulation to give additional support.

⁴Roofing, Siding, Insulation, Vol 58 (June 1981), p 50.



Figure 5. Lisi America Isophenol Board.

^{*}Refers to insulation capabilities



Figure 6. Johns-Manville "Money-Clip" system. (From Johns-Manville Brochure, PB-46A 9-78, p 1.)

5 FIELD AND SITE INVESTIGATIONS

Site inspections or occupant reports about the systems were obtained to supplement the manufacturers' literature and data.

Sprayed Systems

The Union Carbide Corporation at Oak Ridge, TN, reported on two installations of sprayed cellulose. In a warehouse building, no problems were reported (Figure 2); however, in a metal building used for sandblasting, the material did not adhere to the metal surfaces and had fallen off in some areas (Figure 9). The failure occurred mainly because of poor surface preparation and failure to seal the insulation surface.

Board-Applied System

One application of phenolic resin board was inspected. The building was of concrete construction and originally had 1 1/2 to 2 in. (38 to 51 mm) of

cellulose spray-applied to the underside of the concrete deck. Condensation at the deck-insulation interface had caused failure of the application, and it was removed and replaced with 2 1/2 in. (64 mm) of phenolic board. The specifications called for adhesive application; however, incomplete removal of the cellulose material prevented satisfactory bonding of the phenolic boards to the concrete deck, so they were attached using powder-actuated nails driven through cleats. The inspectors noted that the insulation appeared to be too frangible for this type of installation, tending to crack and spall at the fasteners. In addition, there were many gaps between the boards and voids where the material was cored to install hangers for the suspended ceilings.

Proprietary Accessories System

The 136th Civil Engineering Flight (Texas ANG) at Hensley Field, Dallas, TX, provided information about J-M "Money Clip" systems installed in a warehouse and an engine maintenance shop. The warehouse had not been insulated when it was originally built and the maintenance shop's original insulation had deteriorated.

Two significant observations were made when the systems were installed. The vinyl extrusions used for the "clips" are sensitive to high heat; as a result, the gas-fired unit heaters that were installed within 5 ft (1.5 m) of the extrusions softened and deformed them. This was corrected by using hangers and cement-asbestos sheets to isolate the unit heaters. There was also some difficulty closing off the joint at the ceiling-sidewall intersection, so the system had to be modified during installation to seal the ends of the insulation. To date, there have been no major problems with either installation.

Contractor-Designed Systems

Union Carbide provided information about a building where insulation was supported on chicken-wire between steel bar joists (Figure 10). Pins and washers were used as temporary supports, and the joints between runs of insulation were taped. The chicken-wire provided permanent support.

A similar type of installation was reported at the White Sands Missile Range in New Mexico and at the Kraft Food Plant in Champaign, IL. At White Sands, some of the batts were supported with permanent pins welded to the underside of the steel roof (Figure 11). The Kraft Plant used an adhesive-applied pin, but did not use chicken-wire for support. The pins were clipped after the insulation was installed and then sealed with aluminum tape.



Figure 7. Completed "Money-Clip" installation.




Figure 8. Owens-Corning Fiberglas "Energy Miser" system. (From The Energy Miser System [Owens-Corning].)




Figure 9. Deteriorated sprayed cellulose insulation.




Figure 10. Insulation batts supported on chicken-wire.




Figure 11. Installation of batts at White Sands Missile Range.

6 SUMMARY OF SYSTEMS

Table 1 lists the identified systems and products, the data collected, and the data's relationship to the criteria for evaluation.

Table 1
Comparison of Insulation Retrofit Systems

| | National Cellulose Corporation | Thermo Products Thermocon (Cellulose) | Thermax (Polyiso- cyanurate) | J-M RPMD (Fiberglass) | J-M "Money Clip" | Lisi America (Phenolic) | OCF (Fiberglass) |
|-------------------------------------|--------------------------------------|--|---|---|---------------------|--|-------------------------------|
| R THERMAL | 4.54/In. | 4.59/In. | 40F: 8/ln. 75F:7.2/ln. | 2.92/ln. | Varies | 4.4-4.9 | Varies |
| MOISTURE EFFECT | | 10-72% After 24 hr @ 90% R.H. | None Vent Space Above | Absorbs | Absorbs | None to Low | Absorbs |
| AGING EFFECT | None | | Sold With "Aged" R-Values | None | None | Stable | None |
| TEMPERATURE EFFECT | 150-180 F | | 100 F to +250 F | | | 350 F Max. | None |
| WATER VAPOR TRANSMISSION RATE | | Permeable | Foam Is Permeable 0.5 "0" Perm With Foil Facers | Permeable Foil Faces Reduce Rate | .05 Perms | Low Absorption Rate | lntegral Vapor Retarder |
| EXPANSION EFFECT | | None | None | None | None | Stable | None |
| SHAPE | Loose- 4-4.5 In. | Spray | Foil-Faced Slabs 4 ft Wide | Batts W/ Foil Face | Slabs & Batts | Slabs, 2 × 4' 2 × 3' 2 × 3 × 4' bun | Batts & Roll |
| WEIGHT | 2.51 pcf | 2.5 pcf | 2.1-2.3 pcf | | | 2-4 pcf | |
| COMPRESSIVE STRENGTH | | | 25-30 psi | | | 40-60 psi | |
| CHEMICAL REACTION | | Non- Corrosive | | | | Resistant to Acids, Bases, Solvents | None |

Table 1 (Continued)

| | National Cellulose Corporation | Thermo Products Thermocon (Cellulose) | Thermax (Polyiso- cyanurate) | J-M RPMD (Fiberglass) | J-M "Money Clip" | Lisi America (Phenolic) | ()(F (Fiberglass) |
|-----------------------|---|--|--|----------------------------------|---|-----------------------------------|----------------------|
| FIRE RESISTANCE | Surface Char. Class I F.S.<25 | FS 10/25 Fuel 5 Smoke 0 | Req. Cover In Sensitive Areas | UL 25/50 | FS 0-25 Smoke 0-50 | FS 5 Fuel 0 Smoke 5 | UL 25/50 |
| TOXICITY | NR*** | NR | NR | NR | NR | NR | NR |
| APPEARANCE | Textured Surface | | Foil-Faced Taped Joint | Foil-Faced | White Scrim | Rigid Plastic | Plastic Face |
| APPLICATION SYSTEM | Spray | Spray W/Sealer | Direct Attach or Grid Susp. | Secured Between Joists | Clipped to Girts | Adhesive | Roll & Clips |
| CODE | | | | | | | |
| COMPLIANCE | SS-S-11A HH-I-515D FM-Corner Test UL-Approved ICBO | Corner Test | River- Banks BOCA ICBO SBC FHA #933 | UL HFC 25/50 | | | All |
| COST | \$0.39/Sq Ft 1 In. | | | R-11:\$180/MBF R-19:\$259/MBF | 1/2" Board & Batts \$1.54/ft ² | \$0.2226 /Bd Ft* \$0.4047** | |
| OTHER | 15-20 yr Life. Surface Prep Vital | | Not for Resid. Applic. w/o Covering | | | Unlimited Life Exp. | New System |

^{*}For $2 \times 4'$ and $2 \times 3'$ slabs

7 CONCLUSIONS

Criteria were developed for evaluating the products and systems available for upgrading the thermal properties of low-slope roofs by applying insulation to the roofs' undersides. It was found that these criteria could reasonably be applied to appraise the various systems identified by the market survey conducted during this investigation.

The evaluation showed that only a limited number of products available commercially meet the requirements for this application.

Johns-Manville and Owens-Corning Fiberglas each offer a completely integrated, thermal/finished ceiling system applicable to a prefabricated steel building or similar structure. These systems can accommodate different thicknesses of insulation to match the depth of the existing roof purlins, without any difference in

^{**}For 2 × 3 × 4' bun

^{***}Not Reported

installation methods. However, only the Johns-Manville system was on the market at the time of the investigation, so it is not possible to compare it with the Owens-Corning Fiberglas system.

The Celotex Corporation offers a foil-faced insulation board. A suspended grid can be used with this product, or it can be fastened directly to roof purlins with self-tapping screws.

Lisi America offers a rigid phenolic foam board

designed to be applied using mastics as adhesives. Proper surface preparation is essential to successful installation of this material, as adhesives will not bond to a dirty or dusty surface, and the board cannot be applied to a surface that is not flat. The use of mechanical fasteners may cause the board to spall and break.

Thermo Products Company and National Cellulose both offer cellulose material that can be sprayed in place.

APPENDIX A: MARKET SURVEY QUESTIONNAIRE

MATERIAL OR SYSTEM FOR INSULATION RETROFIT OF BUILT-UP ROOFS

| Name and Address of Manufacturer(s) | | | | |
|-------------------------------------|---|--|--|--|
| | duct/System | | | |
| Describe ma | terial system. | | | |
| What i | s it chemically? | | | |
| • | Composition | | | |
| ł | Reactions | | | |
| 1 | Use Restrictions | | | |
| | Age Stability | | | |
| 1 | Reaction to fire | | | |
| What i | s it physically? | | | |
| : | Shape | | | |
| : | Size | | | |
| | Appearance | | | |
| , | List physical properties and specifications | | | |

| List thermal properties and specifications |
|--|
| Age stability |
| Physical properties |
| Thermal properties |
| How is material/system packaged and shipped and stored |
| Does it influence building appearance |
| How - |
| Interior |
| Exterior |
| Utility of material/system |
| May the material/system be installed independent of the type of roof construction? |
| To what types of roof decks and/or roof constructions may the material/system be installed? |
| What types of roof decks and roof constructions are not suitable for the application of this product system? |

Describe how the product/system should be installed.

| What auxilliary materials must be purchased for installation of the product/system (such as nails, glue, vapor-barrier, etc.)? |
|---|
| I ist each together with its applicable ASTM, MIL and Federal specs. |
| Are there any restrictions on application/installation? |
| Does installation require any cosmetic or structural changes to the building (such as a new BUR membrane, increased height of roof curbs, expansion joints, edges, etc.)? |
| What special skills or training are required of the installer? |
| Cost of material/system What is a typical detailed installed cost by element for your product/system? |
| What is the anticipated service life of your product/system? |
| Describe routine maintenance required, its cost and frequency. |
| With what building codes does the material/system comply? |
| List all public specifications and standards with which the product/system complies. |
| ASTM |
| ANSI |
| MIL |
| Federal |

Voluntary Product Standard

NFPA

UL

FM

Other

APPENDIX B: FIELD INFORMATION USED FOR DEVELOPMENT OF LOW-SLOPE RETROFIT INSULATION EVALUATION CRITERIA

Thermal Properties and Criteria

Thermal Conductivity

Select the proper thickness of insulation to provide the desired or specified thermal conductance (conductance = conductivity : thickness).

Make life-cycle cost comparisons of candidate insulations. Note that a simple comparison of installed costs will usually suffice unless regular maintenance of an exposed, decorative surface is a consideration.

Effect of Moisture on Thermal Conductivity

There are no public test methods for this quality. Compare suppliers' or published data on candidate insulations. Personal judgment based on anticipated climatic and environmental exposure should be used.

Effect of Age on Thermal Conductivity

There are no public test methods for this quality, except Federal Specification HII-1-530, which applies to urethane and isocyanurate insulations. Compare suppliers' or published data on candidate insulations. It is suggested that the time rate of change in thermal conductivity in the installed environment shall not exceed that for polyurethane foam panels faced on two sides with aluminum foil.

Effect of Temperature on Thermal Conductivity

Manufacturers of thermal insulations may report thermal conductivity measured at different temperatures. Thermal conductance values for different insulations should be compared only when testing was done at the same temperature.

Physical Properties and Criteria

Shape

This is for information only.

Dimensions

Frequently for information only, Thickness of above-deck insulation may require reconstruction of roof edges, curbs, gutters, etc.

Weight

Frequently for information only Sometimes it may be necessary to consider the effect of added weight on the load-bearing capabilities of the present

deck and support structure. Building code references to roof loading may sometimes be a consideration.

Strength and Rigidity

Frequency for information only. It may be necessary to consider certain aspects of strength in some applications where one or more of the following pertain:

- 1. The insulation will bridge an unsupported span
- 2. The insulation will carry a load from foot or wheel traffic.
- 3. The insulation will interface with the support of roof top or ceiling fixtures.

Chemical Reactions

The insulation shall not decompose or give off noxious or toxic fumes under normal service conditions which shall include exposure to liquid water

The insulation shall not have a corrosive reaction with materials it may contact during normal service conditions and anticipated service life.

Reactions to Fire

The insulation shall comply with local building code and pertinent insurance requirements for performance in fire resistance tests. Such tests may include ASTM F 84 for materials installed below the roof deck and Underwriters' Laboratories of Factory Mutual Tests for materials installed above the roof deck.

Toxicity of fumes and ease of extinguishing are also of concern, but there are no accepted test methods for these qualities.

Appearance of Installed Product/System

Does the product affect the appearance of the building? Describe the effect, if any.

Criteria for Inside Exposure

Color and surface texture shall be selected by the purchaser.

Depth, weight, thickness, and appearance of attachment shall be approved by the purchaser.

Criteria for Outside Exposure

Changes in roof edge height, curbs, and parapets shall be approved by the purchaser.

Describe in detail how the material/system is applied.

Material/System Installed Below Roof Deck

Is the material/system fastened to the roof deck?

How?

Is the material/system suspended below the roof deck?

How?

Is it supported?

What vapor retarder requirements are introduced by the material/system?

What ventilation requirements are introduced by the material/system?

Describe in detail how the material/system is applied.

Product/System Performance

Describe all available guarantees or warranties. What is the anticipated service life of the product/system?

Specification and Code Compliance

List building code(s) compliance. List specifications and standards compliance.

Packaging, Shipping and Storage (information only)
Size of shipping container.

Number of pieces per package (does not apply to bulk insulation).

Coverage per package in square feet.

Weight per package.

Number of packages per truckload.

Number of packages per carload.

Storage instructions.

APPENDIX C: TIMA TESTS ON SPRAYED CELLULOSE INSULATION

SUMMARY **TIMA SPRAYED CELLULOSE TESTS** THERMAL AND WATER VAPOR TRANSMISSION

1. THERMAL TESTS

EQUIPMENT

- Calibrated Hot Box as described m ASTM STP 544, 1974. Test area time feet by fourteen feet; cold side at 0 F, warm side at 75°F.

MATERIAL

~ Sprayed Cellulose was applied (by Manufacturer A or B) to a full scale roof section composed of a typical metal building roof sheets attached to three nine foot purlins spaced five feet on centers. Fastener spacing when testing Manufacturer A was two per foot and when testing Manufacturer B product was one per foot. In both tests, the intended applied thickness was to be 1.1/2''.

TEST RESULTS - Manufacturer A at an average

thickness of 1.92" and an

average density of 5.3 pcf.

Initial "R" Value - 4.1

"U" Value - 0.24

After Ten Days Conditioning*

"R" Value - 3.2

"U" Value - 0.31

Manufacturer B at an average thickness of 1.95" and an average density of 5.3 pcf:

Initial "R" Value - 4.4

"U" Value - 0.23

After Ten Days Conditioning*

"R" Value - 3.1

"U" Value - 0.32

*Conditioning was accomplished by exposing the insulated roof section to an environment of 75°F and 50° RH with a 0°F temperature on the opposite side of the roof section. The average moisture absorption as measured by per cent increase in insulation weight was 84% for Manufacturer A and 120% for Manufacturer B.

II. WATER VAPOR TRANSMISSION TESTS

EOUIPMENT - Full scale WVT test fixture for measuring daily moisture gain to 1.0 lb, on a five foot by ten foot test section; cold side at 0°F, warm moise side at 75°F. 50% RH.

CERL DISTRIBUTION

8th USA. Kores

```
chief of Engineers
ATTN: Tech Monitor
ATTN: DAEN ASI L (2)
                                                                                                                  um
ATTM: facilities Engineer
Cameron station 22314
Fort cesley J. McMair 20319
Fort Myer 22211
  ATTN:
                   DAEN-CCP
DAEN-CWE
DAEN-CWE
DAEN-CWM-
   ATIM
   ATTH
                                                                                                                                                                                                                              IMC ATTN MTML A 20015
ATTN Facilities Engineer
Uakland Army Base 94626
Bayonne MUT 07002
                    UAEN-CHU
DAEN-CHP
DAEN-MP
   ATIM
   ATTN
ATTN
                                                                                                               416th Engineer Command 60623
   ATTH
                    DAE N-MP
                                                                                                              ATTN. facilities Engineer
   ATTN:
                   DAEN-MPL
DAEN-MPU
                                                                                                                                                                                                                                     Sunny Point HUT 28461
                                                                                                              USA Japan (USARJ)
                                                                                                                   Cn, FE Div. AJEN-FE 96343
Fac Engr (Honshu) 96343
Fac Engr (Ukinawa) 96331
                                                                                                                                                                                                                          NARADCOM, ATTN URUNA-F 071160
                    DAE N-MPR -A
   ATTN
                   DAEN-RD
DAEN-RDC
DAEN-RDM
                                                                                                                                                                                                                          TARLOM, Fac. Jiv. 48090
   ATTN:
   ATTM
                 DAEN-RM
UAEN-ZC
   ATTH
                                                                                                              ROK/US Combined Forces Command 96301
ATTN: EUSA-HHC-CFL/Engr
                                                                                                                                                                                                                          TECUM, ATTN. UNSTE-LU-F 21005
   ATTN:
   ATTM
                  DAEN-ZCE
                                                                                                                                                                                                                          TRADUL
                                                                                                             US Military Academy 10990
ATTN Facilities Engineer
ATTN: Dept of Geography &
Computer Science
ATTN: DSCPER/MACH-A
                                                                                                                                                                                                                              RUDOL ATTN. ATEN-FE
ATTN. Facilities Engineer
Fort Belvoir (2000)
Fort Benning (1905)
Fort Bliss (7991)
  ATTN:
ATTN:
                  DAEN-ZCM
  FESA, ATTN: Library 22060
  US Army Engineer Districts
ATTN: Library
                                                                                                                                                                                                                                   Carlisle Barracks 1/013
Fort Chaffee 1/2902
                                                                                                              Engr. Studies Center 20315
ATTN: Library
                                                                                                                                                                                                                                     Fort Ula UBb4U
           Alaska 99501
                                                                                                                                                                                                                                   Fort List 19940
Fort List 1994
Fort Lordon 30905
Fort Hamilton 11252
Fort Benjamin Harrison 46216
Fort Jackson 29207
            Al Batin 09616
           Albuquerque 87103
Baltimore 21203
Buffalo 14207
Charleston 29402
                                                                                                              AMMRC, ATTN: DRXMR-WE U2172
                                                                                                              USA ARRCOM 61299
ATTN: DRCIS-RI-I
ATTN: DRSAR-IS
            Chicago 60604
Detroit 48231
Far East 96301
                                                                                                                                                                                                                                     Fort Knox 401cl
                                                                                                                                                                                                                                   Fort know 40121

Fort Lee 23801

Fort McLlellan 30205

Fort Monroe 23651

Fort Mucker 36362

Fort 5111 73503
                                                                                                                  DARCOM - Dir., Inst., & Svcs.
ATTN: Facilities Engineer
ARRADCOM D7801
Aberdeen Proving Ground 21005
Army Matls. and Mechanics Res. Ctr
Corpus Christi Army Depot 78419
Harry Diamond Laboratories 207d3
Dugway Proving Ground 84022
Jefferson Proving Ground 47250
Fort Monmouth 07703
Letterhenny Army Depot 17201
            Fort Worth 76102
Galveston 77550
          Galveston 7.7550
Huntington 25721
Jacksonville 32232
Japan 96343
Kansas City 64106
Little Rock 72203
Los Angeles 90053
Louisville 40201
Memphis 38103
Mobile 36628
Mashville 37202
New Orleans 70160
New York 10007
Norfolk 23510
Dmaha 68102
                                                                                                                                                                                                                                    Fort Leonard Wood 65473
                                                                                                                                                                                                                          TSARCUM, ATTN. STSAS-F 63120
                                                                                                                             Fort Monmouth 07703
Letterkenny Army Depot 17201
Natick RAD Ctr. 01760
New Cumberland Army Depot 17070
Pueblo Army Depot 81001
Red River Army Depot 75501
Redstone Arsenal 35809
                                                                                                                                                                                                                              ATTN: Facilities Engineer
                                                                                                                                                                                                                                   Fort Huachuca 8561.
Fort Hitchie 21719
                                                                                                                                                                                                                          WESTCOM
ATTN: Facilities Engineer
                                                                                                                             Redstone Arsenal 61299
Savanna Army Depot 61074
Sharpe Army Depot 95331
Seneca Army Depot 14541
            Omaha 68102
Philadelphia 19106
                                                                                                                                                                                                                                   Fort Shafter 96858
                                                                                                                                                                                                                           SHAPE 09055
            Pittsburgh 1522
Portland 97208
                                         15222
                                                                                                                                                                                                                              ATTN. Survivability Section, UCB-UPS
Infrastructure Branch, LAMUA
            Rivadh 09038
                                                                                                                              Tobyhanna Army Depot 18466
            Rock Island 61201
Sacramento 95814
San Francisco 94105
                                                                                                                             Tooele Army Depot 84074
Watervliet Arsenal 12189
                                                                                                                                                                                                                           HQ USEBCOM 09128
ATTN: ECJ 4/7-LUE
                                                                                                                             Yuma Proving Ground 85364
White Sands Missile Range 88002
            Savannah 31402
Seattle 98124
                                                                                                                                                                                                                         Fort Belvoir, VA 22060
ATTN: ATZA-DIE-EM
ATTN: ATZA-DIE-SW
ATTN: ATZA-DIE-SW
ATTN: ATZA-FE
ATTN: Engr. Library
ATTN: Canadian Liaison Office (2)
ATTN: IWR Library
           Seattle 98124
St. Louis 63101
St. Paul 55101
fulsa 74102
Vicksburg 39180
Walla Walla 99362
Wilmington 28401
                                                                                                             DLA ATTN: DLA-WI 22314
                                                                                                             FORSCOM
                                                                                                                  FORSCOM Engineer, ATTN: AFEN-FE
ATTN: Facilities Engineer
Fort Buchanan 00934
US Army Engineer Divisions
ATM: Library
Europe 09757
Huntsville 35807
Lower Mississippi Valley 39180
Middle East 09038
Middle East (Rear) 22601
Missouri River 68101
New England 02154
North Atlantic 10007
North Central 60605
North Pacific 97208
Onio River 45201
Pacific Ocean 96958
South Atlantic 30303
South Pacific 94111
Southwestern 75202
                                                                                                                       Fort Buchanan 0093
Fort Campbell 42223
Fort Carson 80913
Fort Devens 01433
Fort Drum 13601
Fort Hood 76544
                                                                                                                                                                                                                          Cold Regions Research Engineering Lab U3/55
ATTN: Library
                                                                                                                                                                                                                           ETL, ATTN: Library 22060
                                                                                                                      Fort Hood 76544
Fort Indiantown Gap 17003
Fort Irwin 92311
Fort Sam Houston 78234
Fort McCherson 30330
Fort George G. Meade 20755
Fort Ord 93941
Fort Polk 71459
Fort Richardson 99505
Fort Richardson 99505
Fort Richardson 60037
Fort Sheridan 60037
Fort Stewart 31313
Fort Malmeright 99703
                                                                                                                                                                                                                          Waterways Experiment Station 39180
ATTN: Library
                                                                                                                                                                                                                           HQ, XVIII Airborne Corps and 28307
                                                                                                                                                                                                                           Ft. Bragg
ATTN: AFZA-FE-EE
                                                                                                                                                                                                                          Chanute AFB, IL 61868
3345 CES/DE, Stop 27
                                                                                                                                                                                                                           Norton AFB 92409
ATTN: AFRCE-MX/UEE
Southwestern 75202

US Army Europe
MQ, 7th Army Training Command 09114
ATTN: AETTG-DEH (5)
MQ, 7th Army OOCS/Engr. 09403
ATTN: AEEMS-EH (4)
Y. Corps 09079
ATTN: AETYDEH (5)
YII. Corps 09154
ATTN: AETSDEH (5)
Zist Support Command 09325
ATTN: AERH (5)
Berlin 09742
ATTN: AEBA-EN (2)
Southern European Task Force 09168
ATTN: AESC-ENG (3)
Installation Support Activity 09403
ATTN: AEUES-RP
                                                                                                                                                                                                                           NCEL 93041
ATTN: Library (Code LUBA)
                                                                                                                        Fort Walnuright 99703
Yancouver Bks. 98660
                                                                                                                                                                                                                           Tyndall AFB, +L 32403
AFESC/Engineering & Service Lab
                                                                                                                  NITN: HSLO-F 7R234
ATTN: Facilities Engineer
Fitzsimons Army Medical Center 80240
Walter Reed Army Medical Center 20012
                                                                                                                                                                                                                           Defense Technical Info. Center 22314
ATTN: DDA {12}
                                                                                                                                                                                                                          Engineering Societies Library 10017
New York, NY
                                                                                                              INSCOM - Ch. Instl. Div.
ATTM: Facilities Engineer
Arlington Hall Station (2) 22212
Vint Hill Farms Station 2218b
                                                                                                                                                                                                                           National Guard Bureau 20310
Installation Division
                                                                                                                                                                                                                           US Government Printing Office 22304
Receiving Section/Depository Copies (2)
```

Chief of Engineers 20314 ATTN: DAEN-MPO-B ATTN: DAEN-MPZ-A ATTN: DAEN-MPR (2) ATTN: DAEN-ZCP US Army Engineer District New York 10007
ATTN: Chief, Design Br Pittsburgh 15222 ATTN: Chief, ORPCD ATTN: Chief, Engr Div Philadelphia 19106 ATTN: Chief, NAPEN-D Baltimore 21203 ATTN: Chief, Engr Div Norfolk 23510 ATTN: Chief, NAOEN-M ATTN: Chief, NAOEN-D Huntington 25721 ATTN: Chief, ORHED-F Wilmington 28401 ATTN: Chief, SAWCO-C ATTN: Chief, SAWEN-D Charleston 29402 ATTN: Chief, Engr Div Savannah 31402 ATTN: Chief, SASAS-L Jacksonville 32232 ATTN: Const Div
Mobile 36628
ATTN: Chief, SAMEN-D
ATTN: Chief, SAMEN-F
ATTN: Chief, SAMEN Nashville 37202 ATTN: Chief, ORNED-F Memphis 38103 ATTN: Chief, Const Div ATTN: Chief, LMMED-D Vicksburg 39180 ATTN: Chief, Engr Div ATTN: Chief, En Louisville 40201 ATTN: Chief, Engr Div Detroit 48231 ATTN: Chief, NCEED-T St. Paul 55101 ATTN: Chief, ED-D ATTN: Chief, ED-F Chicago 60604 ATTN: Chief, NCCCO-C ATTN: Chief, NCCED-F Rock Island 61201 ATTN: Chief, Engr Div ATTN: Chief, NCRED-F St. Louis 63101 ATTN: Chief, ED-D Kansas City 64106 ATTN: Chief, Engr Div Omaha 68102 ATTN: Chief, Engr Div New Orleans 70160 ATTN: Chief, LMNED-DG Little Rock 42203 ATTN: Chief, Engr Div Tulsa 74102 ATTN: Chief, Engr Div Ft. Worth 76102 ATTN: Chief, SWFED-D ATTN: Chief, SWFED-F Galveston 77550
ATTN: Chief, SWGAS-L
ATTN: Chief, SWGCO-C
ATTN: Chief, SWGED-DC ATTN: Chief, SWGED-DC Albuquerque 87103 ATTN: Chief, Engr Div Los Angeles 90053 ATTN: Chief, SPLED-F San Francisco 94105 ATTN: Chief, Engr Div Sacramento 95814 ATTN: Chief, SPKED-D ATTN: Chief, SPKED-D ATTN: Chief, SPKCO-C Far Fast 96301 Far East 96301 ATTN: Chief, Engr Div

US Army Engineer District Portland 97208 ATTN: Chief, DB-6 ATTN: Chief, FM-1 ATTN: Chief, FM-2 Seattle 98124 ATTN: Chief, NPSCO ATTN: Chief, NPSEN-FM ATTN: Chief, EN-DB-ST Alin: Chief, EN-DB-Si Walla Walla 99362 ATTN: Chief, Engr Div Alaska 99501 ATTN: Chief, NPASA-R US Army Engineer Division New England 02154 ATTN: Chief, NEDED-T ATTN: Laboratory
ATTN: Chief, NEDCD
Middle East (Rear) 22601
ATTN: Chief, MEDED-T North Atlantic 10007 ATTN: Chief, NADEN South Atlantic 30303 South Atlantic 30303
ATTN: Laboratory
ATTN: Chief, SADEN-TC
ATTN: Chief, SADEN-TS
Hunstville 35807
ATTN: Chief, HNDED-CS
ATTN: Chief, HNDED-M
ATTN: Chief, HNDED-M
ATTN: Chief, HNDED-M Lower Mississippi 39180 ATTN: Chief, LMYED-G Ohio River 45201

ATTN: Laboratory
ATTN: Chief, Engr Div
Missouri River 68101
ATTN: Chief, MRDED-G
ATTN: Laboratory Southwestern 75202 ATTN: Laboratory
ATTN: Chief, SWDED-MA
ATTN: Chief, SWDED-TG
South Pacific 94111 ATIN: Laboratory
Pacific Ocean 96858
ATTN: Chief, Engr Div
ATTN: FM&S Branch
ATTN: Chief, PODED~D
North Pacific 97208 ATTN: Laboratory ATTN: Chief, Engr Div

6th US Army 94129 ATTN: AFKC-EN

7th US Army 09407 ATTN: AETTM-HRD-EHD

ATTN: CFAR-EN

US Army Foreign Science and Tech Center ATTN: Charlottesville, VA 22901 ATTN: Far East Office 96328

USA ARRADCOM 07801 ATTN: DRDAR-LCA-OK

West Point, NY 10996 ATTN: Dept of Mechanics ATTN: Library

Ft. Belvoir, VA 22060 ATTN: ATSE-TD-TL (2) ATTN: Learning Resource Center ATTN: British Liaison Officer (5)

Ft. Benning, GA 31905 ATTN: ATZB-FE-EP ATTN: ATZB-FE-BG

Ft. Clayton Canal Zone 34004 ATTN: DFAE

Ft. Leavenworth, K5 66027 ATTN: ATZLCA-SA

Ft. Lee, VA 23801 ATTN: DRXMC-D (2)

Ft. McPherson, GA 30330 ATTN: AFEN-CD

Ft. Monroe, VA 23651 ATTN: ATEN-AU (3) ATTN: ATEN-FE-ME ATTN: ATEN-FE-BG (2)

Ft. Richardson, AK 99505 ATTN: AFZT-FE-E

Rocky Mountain Arsenal 80022 ATTN: SARRM-CO-FEP

USA-WES 39180 ATTN: C/Structures ATTN: Soils & Pavements Lab

Naval Facilities Engr Command 22332

ATTN: Code 04 ATTN: Code 2013 C Port Hueneme, CA 93043 ATTN: Morell Library

Commander (Code 2636) 93555 Naval Weapons Center

Bolling AFB, DC 20332 AF/LEEEU

Little Rock AFB ATTN: 314/DEEE

Patrick AFB, FL 32925

ATTN: XRU

Tinker AFB, OK 73145 2854 ABG/DEEE

Tyndall AFB, FL 32403 AFESC/TST

Airports and Const Services Dir Technical Info Reference Center Ottawa, Ontario, Canada KIA UNS

Bldg Research Advisory Board 20418 Federal Aviation Administration 20540 Dept of Transportation Library 20590 HQ. Combined Field Army (ROK/US) 96358 Transportation Research Board 20418

> Division of Building Research National Research Council Ottawa, Untario, Canada K1A OR6

National Defense Headquarters Director General of Construction Ottawa, Ontario, Canada KIA OK2

> 136 2-1-82

Rosenfield, Myer J
Insulation retrofit under low-slope roofs / by Myer J. Rosenfield, Donald E.
Brotherson. -- Champaign, IL: Construction Engineering Research Laboratory;
available from NTIS, 1981.
26 p. (Technical report; M-308)

1. Flat roofs - thermal properties. 2. Insulation (heat). I. Brotherson, Donald E. II. Title. III. Series: U. S. Army. Construction Engineering Research Laboratory. Technical report; M-308.

